6050



Attorney Docket No.: 2207/11266
Assignee: Intel Corporation

<u>IN THE UNITED STATES PATENT AND TRADEMARK OFFICE</u>

APPLICANTS: Kenneth DROTTAR et al.

SERIAL NO. : 09/891,466

FILED: June 27, 2001 Certificate

PATENT NO. : 6,943,606 B2 SEP **2** 1 2006

ISSUED : September 13, 2005

FOR : PHASE INTERPOLATOR

M/S: CERTIFICATE OF CORRECTION BRANCH Commissioner for Patents P.O. Box 1450

Alexandria, VA 22313-1450

Certificate of Mailing

I hereby certify that this correspondence is being deposited with the United States Postal Service as first class mail in an envelope addressed to: M/S: CERTIFICATE OF CORRECTION BRANCH, Commissioner for Patents, P.O. Box 1450, Alexandria, VA 22313-1450 on

Date: September 12, 2006

Signature Pilar Rodriguez

REQUEST FOR CERTIFICATE OF CORRECTION

Dear Sir:

We have compared the above patent with the application as filed and have found errors in the printing of the patent. We respectfully request that the enclosed Certificate of Correction on Form PTO-1050 be issued correcting the mistakes set forth therein under authority of 35 U.S.C. §254. The exact column and line number where the errors occurred in the patent are listed on the enclosed certificate.

98748 1203 11.521.211 000000.TS 119800 8899305 01 F984911 100880 11 Patent No 6,943,606 B2 Issued: September 13, 2005

The errors that appear in the patent are various typographical errors made by the Applicant and therefore, a fee is required.

Please charge payment of the Certificate of Correction fee of \$100.00 to Deposit Account No. 11-0600. The Office is hereby authorized to charge any additional fees, or credit any overpayments, to Deposit Account No. 11-0600.

Respectfully submitted,

KENYON & KENYON LLP

Dated: September 12, 2006

By:

Sumit Bhattacharya

(Reg. No. 51,469)

KENYON & KENYON LLP 333 West San Carlos St., Suite 600 San Jose, CA 95110

Telephone:

(408) 975-7500

Facsimile:

(408) 975-7501

Under the Paperwork Reduction Act of 1995, no persons are required to respond to a collection of information unless it displays a valid OMB control number. (Also Form PTO-1050)

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO : 6,943,606 B2

Sept. 13, 2005

INVENTOR(S): Kenneth DROTTAR et al.

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Column 6, Line 17 "coupled respective ones" should be --coupled to

respective ones --

Column 6, Line 49 "a rise and fall times that are" should be

-- rise and fall times that are--

"is about 30/0.32" should be --is about Column 6, Line 56

30/0.32; --

"said transistor operated" should be --said Column 8, Line 6

transistor is operated --

Column 8, Line 16 "is about 3/0.32" should be --is about

30/0.32; --

KENYON & KENYON LLP

MAILING ADDRESS OF SENDER: 333 W. San Carlos, Suite 600 PATENT NO. 6,943,606 B2

San Jose, CA 95110

Atty. Ref.: 2207/11266 Telephone: (408) 975-7500 Facsimile: (408) 975-7501 Date: Sept. 12, 2006

No. of additional copies

This collection of information is required by 37 CFR 1.322, 1.323, and 1.324. The information is required to obtain or retain a benefit by the public which is to file (and by the USPTO to process) an application. Confidentiality is governed by 35 U.S.C. 122 and 37 CFR 1.14. This collection is estimated to take 1.0 hour to complete, including gathering, preparing, and submitting the completed application form to the USPTO. Time will vary depending upon the individual case. Any comments on the amount of time you require to complete this form and/or suggestions for reducing this burden, should be sent to the Chief Information Officer, U.S. Patent and Trademark Office, U.S. Department of Commerce, P.O. Box 1450, Alexandria, VA 22313-1450. DO NOT SEND FEES OR COMPLETED FORMS TO THIS ADDRESS. SEND TO: Commissioner for Patents, P.O. Box 1450, Alexandria, VA 22313-1450.